

Table of Contents

Foreword	ix
Executive Summary of Findings	x
Technical Findings	x
Management Findings	x
Regulatory Findings	xi
Chapter 1 Scope of Investigation and Methodology	1
Nature of Report	1
Scope of Investigation and Report	1
Investigation Methodology	2
Structure of the Report	3
Chapter 2 Drilling for Oil in Deepwater	5
Oil and Gas in Deepwater	5
How to Drill a Deepwater Well	8
Chapter 3 Background on the Macondo Well, the <i>Deepwater Horizon</i> , and the Companies Involved	25
The Macondo Well	25
The <i>Deepwater Horizon</i>	26
Companies and Individuals Involved in the Macondo Blowout	30
Chapter 4 Technical Findings.....	35
Underlying Technical Causes	35
Underlying Management Causes	37
Chapter 4.1 Flow Path.....	39
Potential Flow Paths	40
Forensic Evidence Suggests That Hydrocarbons Did Not Flow up the Annulus and Through the Seal Assembly	42
Hydrocarbons Appear to Have Flowed Into and up the Production Casing	48
Technical Findings	52
Chapter 4.2 Well Design.....	53
Deepwater Well Design	53
The Macondo Well Design	55
Drilling the Macondo Well	58
Technical Findings	62
Management Findings	64
Chapter 4.3 Cement.....	67
Well Cementing	67
Preparing for the Macondo Cement Job	77
Designing the Macondo Cement Job	78
Planning for and Installing Centralizers at Macondo	81
Float Collar Installation and Conversion at Macondo	87
Pre-Cementing Wellbore Conditioning at Macondo	90
Cementing Process at Macondo	92
The Float Check at Macondo	93
Cement Evaluation at Macondo	94
Technical Findings	95
Management Findings	102

Chapter 4.4 Foamed Cement Stability	111
Foamed Cement	111
Foamed Cement at Macondo	113
Technical Findings	120
Management Findings	123
Chapter 4.5 Temporary Abandonment	127
Temporary Abandonment	127
Temporary Abandonment at Macondo	128
Technical Findings	135
Management Findings	139
Chapter 4.6 Negative Pressure Test	143
Well Integrity Tests	143
Negative Pressure Test at Macondo	147
Technical Findings	160
Management Findings	161
Chapter 4.7 Kick Detection	165
Well Monitoring and Kick Detection	165
Well Monitoring at Macondo	174
Technical Findings	182
Management Findings	184
Chapter 4.8 Kick Response	193
Well Control Equipment	193
Kick Response at Macondo	195
Technical Findings	198
Management Findings	200
Chapter 4.9 The Blowout Preventer	203
Blind Shear Rams	204
Blind Shear Ram Activation at Macondo	206
ROV Hot Stab Activation at Macondo	208
Automatic Blind Shear Ram Activation at Macondo	208
Potential Reasons the Blind Shear Ram Failed to Seal	212
BOP Recertification	215
Technical Findings	216
Management Findings	217
Chapter 4.10 Maintenance	221
Transocean’s Rig Management System	221
Competing Interests Between Drilling and Maintenance	222
Lack of Onshore Maintenance	222
Maintenance Audits and Inspections	223
Maintenance Findings	224
Chapter 5 Overarching Failures of Management	225
Leadership	225
Communication	227
Procedures	232
Employees	235
Contractors	237
Technology	240
Risk	242
Closing	249

Chapter 6 Regulatory Observations	251
MMS Background	251
MMS Regulations Did Not Address Many Key Risk Factors for the Blowout	253
BOP Recertification	260
Ethical Considerations	261
Endnotes	262
Appendix A Blowout Investigation Team	346
Appendix B Commission Staff.....	347
Appendix C Acronyms	349
Appendix D Chevron Laboratory Report Cover Letter	351
Appendix E Nile and Kaskida.....	353
Schedule When the <i>Deepwater Horizon</i> Arrived at Macondo	353
Request to Suspend Operations at Kaskida	354

Figures and Tables

Figures

Chapter 2|Drilling for Oil in Deepwater

Figure 2.1. Schematic geological cross section.	5
Figure 2.2. Drilling.	9
Figure 2.3. Pore pressure and fracture gradients.	10
Figure 2.4. Casing strings (greatly simplified).	11
Figure 2.5. Rig structures.	12
Figure 2.6. Rig structures.	12
Figure 2.7. Early drilling phases.	14
Figure 2.8. Wellhead assemblies.	15
Figure 2.9. BOP components.	16
Figure 2.10. Flow in a typical mud system.	17
Figure 2.11. Casing hanger.	18
Figure 2.12. Wiper plugs.	18
Figure 2.13. Cementing.	19
Figure 2.14. Perforating the production casing.	20
Figure 2.15. Barriers in a well.	21
Figure 2.16. Simplified AMF control system schematic.	22

Chapter 3| Background on the Macondo Well, the *Deepwater Horizon*, and the Companies Involved

<i>The Deepwater Horizon.</i>	24
Figure 3.1. <i>Deepwater Horizon.</i>	26
Figure 3.2. Main deck.	27
Figure 3.3. Decks.	28
Figure 3.4. Mud pits and moon pool.	28
Figure 3.5. Subsurface portion of the <i>Deepwater Horizon.</i>	29
Figure 3.6. Blowout preventer.	29
Figure 3.7. Blowout preventer.	30
Figure 3.8. <i>Deepwater Horizon's</i> organizational structure.	31

Chapter 4.1| Flow Path

Figure 4.1.1. Possible flow paths for hydrocarbons.	39
Figure 4.1.2. Flow through the seal assembly.	40
Figure 4.1.3. Flow up the production casing.	41
Figure 4.1.4. Exterior of the Macondo production casing hanger and seal assembly.	44
Figure 4.1.5. Interior of the Macondo production casing hanger compared to new equipment.	45
Figure 4.1.6. Undamaged metal edges of the casing hanger and seal assembly.	46
Figure 4.1.7. Halliburton post-cement-job report.	48
Figure 4.1.8. Erosion of the inside of the casing hanger.	49
Figure 4.1.9. 16-inch casing and rupture disks.	50

Chapter 4.2| Well Design

Figure 4.2.1. Artist's rendering of the Macondo well.	53
Figure 4.2.2. Narrow drilling margins.	54
Figure 4.2.3. Annular pressure buildup (APB).	55
Figure 4.2.4. Offset wells and seismic data.	56
Figure 4.2.5. Rupture disks.	57
Figure 4.2.6. Protective casing.	57
Figure 4.2.7. Casing options in deepwater drilling.	58
Figure 4.2.8. Timeline of drilling events.	59
Figure 4.2.9. Cementing a long string vs. cementing a liner.	62

Chapter 4.3 | Cement

Figure 4.3.1. Typical completed cement job.	67
Figure 4.3.2. Sample caliper log data showing open hole diameter by depth.	68
Figure 4.3.3. Centralizer.	68
Figure 4.3.4. Top view of off-centered casing.	69
Figure 4.3.5. Centralizer sub.	69
Figure 4.3.6. Float valve conversion.	70
Figure 4.3.7. Full bottoms up.	70
Figure 4.3.8. Wiper plugs cause cement contamination.	71
Figure 4.3.9. Lift pressure.	72
Figure 4.3.10. Bumping the plugs.	73
Figure 4.3.11. Cement bond log tool.	74
Figure 4.3.12. Remedial cementing—squeeze job.	75
Figure 4.3.13. Centralizer sub (top) and slip-on centralizer with stop collars (bottom).	83
Figure 4.3.14. Gregg Walz April 16, 2010 email to John Guide about centralizers.	84
Figure 4.3.15. Centralizers delivered to the <i>Deepwater Horizon</i> on April 16, 2010.	85
Figure 4.3.16. John Guide April 16, 2010 email to Gregg Walz about centralizers.	85
Figure 4.3.17. Auto-fill float collar.	88
Figure 4.3.18. BP's pre-cementing mud circulation.	91
Figure 4.3.19. Decision tree.	94
Figure 4.3.20. Clogged reamer shoe.	101
Figure 4.3.21. Ball forced through tube.	101
Figure 4.3.22. Page 23 of Halliburton's April 18, 2010 OptiCem™ report.	109

Chapter 4.4 | Foamed Cement Stability

Figure 4.4.1. Foam testing apparatus.	112
Figure 4.4.2. Foam testing apparatus.	112
Figure 4.4.3. Foam testing apparatus.	112
Figure 4.4.4. Halliburton evidence of test times.	118

Chapter 4.5 | Temporary Abandonment

Figure 4.5.1. Planned configuration after temporary abandonment.	128
Figure 4.5.2. Lockdown sleeve.	129
Figure 4.5.3. BP subsea wells organization.	130
Figure 4.5.4. Multiple last-minute revisions to the temporary abandonment procedure.	132
Figure 4.5.5. Bridge plug.	137

Chapter 4.6 | Negative Pressure Test

Figure 4.6.1. Well integrity tests.	143
Figure 4.6.2. Seal assembly test.	144
Figure 4.6.3. Positive pressure test.	145
Figure 4.6.4. Negative pressure test.	146
Figure 4.6.5. End of cement to temporary abandonment.	146
Figure 4.6.6. Preparations for the negative pressure test.	147
Figure 4.6.7. First test failure.	148
Figure 4.6.8. Second test failure.	148
Figure 4.6.9. Negative pressure test progress, 3 p.m. on April 20, 2010.	149
Figure 4.6.10. 4 p.m.	150
Figure 4.6.11. 4:53 p.m.	151
Figure 4.6.12. 4:55 p.m.	152
Figure 4.6.13. 4:58 p.m.	153
Figure 4.6.14. 5:10 p.m.	154
Figure 4.6.15. 5:26 p.m.	155
Figure 4.6.16. 5:53 p.m.	156
Figure 4.6.17. Bladder effect.	157
Figure 4.6.18. 6:40 p.m.	158
Figure 4.6.19. Spacer migration.	159

Chapter 4.7| Kick Detection

Figure 4.7.1. Active pit volume in a closed-loop system.	166
Figure 4.7.2. Active pit volume in a non-closed-loop system.	167
Figure 4.7.3. Hitec data display.	169
Figure 4.7.4. Sperry-Sun data display.	169
Figure 4.7.5. Flow-out sensors and flow line camera.	170
Figure 4.7.6. Transocean’s <i>Deepwater Horizon</i> Emergency Response Manual.	171
Figure 4.7.7. Rig personnel on duty during the final displacement.	174
Figure 4.7.8. Erratic vs. normal flow-out.	175
Figure 4.7.9. Typical flow-out signature vs. spike at 9:08 p.m.	178
Figure 4.7.10. Drill pipe pressure anomalies from 9:01 to 9:14 p.m.	179
Figure 4.7.11. Drill pipe pressure and kill line pressure anomalies from 9:27 to 9:40 p.m.	180
Figure 4.7.12. Last two hours of Sperry-Sun data.	191

Chapter 4.8| Kick Response

Figure 4.8.1. Diverter system.	195
Figure 4.8.2. BOP control panels on the rig floor and bridge.	197
Figure 4.8.3. BOP control panels on the rig floor and bridge.	197
Figure 4.8.4. Transocean’s “procedures for handling gas in the riser.”	201

Chapter 4.9| The Blowout Preventer

Figure 4.9.1. Transporting the <i>Deepwater Horizon</i> BOP.	203
Figure 4.9.2. The <i>Deepwater Horizon</i> blowout preventer stack.	204
Figure 4.9.3. The <i>Deepwater Horizon</i> blowout preventer stack.	204
Figure 4.9.4. Blind shear ram.	204
Figure 4.9.5. Tool joint in the blind shear ram.	205
Figure 4.9.6. <i>Deepwater Horizon</i> blowout preventer’s closed blind shear ram (top view).	207
Figure 4.9.7. AMF system.	209
Figure 4.9.8. BOP’s electrical schematic.	211
Figure 4.9.9. Erosion in the BOP.	212

Chapter 5| Overarching Failures of Management

Figure 5.1. BP internal presentation slide.	226
---	-----

Chapter 6| Regulatory Observations

Figure 6.1. Chapter 3 of the Commission’s full report.	251
Figure 6.2. BOEMRE organizational chart for the Gulf of Mexico region in July 2010.	252
Figure 6.3. MMS regulation 30 C.F.R. § 250.428.	255
Figure 6.4. MMS regulation 30 C.F.R. § 250.401.	257
Figure 6.5. BP’s April 16 application for permit to modify.	258

Tables

Chapter 4.3| Cement

Table 4.3.1. Low pressure observed after circulation established.	90
Table 4.3.2. Plans reduce pre-cement circulation volumes and rates.	92
Table 4.3.3. Cementing volumes.	93
Table 4.3.4. Flow rate and differential pressure needed to convert.	100

Chapter 4.4| Foamed Cement Stability

Table 4.4.1. Halliburton’s internal laboratory data concerning the stability of the Macondo cement slurry.	122
--	-----

Chapter 4.7| Kick Detection

Table 4.7.1. Personnel and places with access to the rig’s Sperry-Sun data.	173
---	-----

Chapter 4.9| The Blowout Preventer

Table 4.9.1. Control pod battery replacements (based on available records).	211
Table 4.9.2. Leaks on the <i>Deepwater Horizon</i> blowout preventer (partial list).	214
Table 4.9.3. Modifications to the <i>Deepwater Horizon</i> blowout preventer.	218-19

Chapter 5| Overarching Failures of Management

Table 5.1. Timeline of changes to the temporary abandonment procedure.	233
Table 5.2. Examples of decisions that increased risk at Macondo while potentially saving time.	246